

9642 - Southern Peak Regional Treatment Center

Child Care - Specialize Group

Physical Address:
700 Fourmile PKWY Canon City, CO 81212
County: Fremont (22)

INSPECTION DATE:
03/23/2010

INSPECTION TYPE:
 REGULAR
 FOLLOW-UP
 PRE-OPERATIONAL
 COMPLAINT

LICENSE STATUS
RECOMMENDATION
 APPROVED
 DENIED

RED→CRITICAL ITEM VIOLATIONS are more likely than other violations to contribute to illness or environmental hazards that may contribute to a disease outbreak. Critical item violations include inappropriate diapering procedures, lack of handwashing, ineffective sanitization and disinfection, ill personnel preparing food or caring for children, unsafe water supply or sewage disposal, vermin infestation, food temperature abuse and uncontrolled toxics.

FOOD SERVICE

07f. FH Handwashing

- ↳ Corrective Action: Corrected On-Site. Correct-By: 03/23/2010
Inspector Comments: KITCHEN 7-103(d) Food handlers in the kitchen are wearing more than a single ring (additional rings and jewelry on wrists).

BLUE→NON-CRITICAL ITEM VIOLATIONS are not directly related to the cause of illness, environmental hazards or disease outbreak, but if uncorrected, could negatively affect the operation of the child care facility. These include a lack of facility cleanliness and poor maintenance of equipment and facilities.

BUILDING

03a. Clean/Good Repair

- ↳ Inspector Comments: KITCHEN 3-101 Ceiling areas are dirty around ceiling vents.
- ↳ Inspector Comments: KITCHEN 3-101 Floor areas dirty inside the Walk-In Refrigerator.

03e. Lighting

- ↳ Inspector Comments: KITCHEN 3-105 In the Storeroom, some bulbs are burned out in ceiling light fixtures

SANITARY FACILITIES & CONTROLS

04d. Plumbing

- ↳ Inspector Comments: LEARNING CENTER 4-301 Sewer gas odors in restroom.
- ↳ Inspector Comments: KITCHEN 4-301 The handsink in the serving line area drains slowly.
- ↳ Inspector Comments: KITCHEN 4-302 The "Y" valve on the mopsink faucet is installed downstream from the built-in vacuum breaker on the faucet, making the built-in vacuum breaker ineffective. Remove the "Y" valve and consider using quick-couple disconnects to attach the chemical feeder and the hose used to fill mop buckets; disconnect these hoses when not being used.

04e. Toilet Facilities



Inspector Comments: KITCHEN 4-407 The restroom ceiling vent is covered with dust.

FOOD SERVICE

07b. Equipment Design



Inspector Comments: KITCHEN 7-101 The front panel on the juice dispenser is damaged and repaired with tape.

ADDITIONAL COMMENTS:

10:20am.

In the kitchen, adequate quat sanitizer in wipe cloth buckets and in the 3-compartment sink, 200 ppm.

An adequate final rinse temperature was measured in the kitchen dishmachine, at least 160 Deg.F at utensil surface.

RECOMMENDED REGULATORY ACTION(S), RESOLUTION(S) & INTERVENTIONS:

CIVCS:

YES

NO

ON-SITE FOLLOW-UP:

YES

NO